Work History Report

Date Produced: 10/13/2026

Account: 19 District Attorneys Office

Reg: MG8073E PA

Vehicle Details FORD E-450 SUPER DUTY SRT AMB. 6.0 2007
white

Cumberland County Courthouse
310 Allen Road
Suite 501
Carlisle
PA
17013-3323

Eng Code / Num V8 6.0L 363CID FI DIESEL T P / **Vin** 1FDXE45P17DB05707 **Mileage** 186844

Invoice Number I002344 **Date** 2/23/2023 **Mileage** 186844 **Job Value** 229.02

Vehicle Details MG8073E PA FORD E-450 SUPER DUTY SRT AMB. 2007

Labor	Value
PM Service check lights,brake and overall safety of vehicle. Replaced air filter and installed new clamp on trans cooler line, added trans fluid.	77.63
State Inspection	51.75

Parts		Qty	Value
CNVWWFliud Clearv	Windshield Washer Fluid	1.00	1.20
CNV84323	Oil Filter	1.00	19.94
CNV15W-40	15w-40 Diesel Oil	14.50	47.85
CNVMAXLIFE ATF	Transmission fluid	2.00	14.38
CNVKE28BX AZ	Hose Clamp 1 516	1.00	0.30
CNVFA-1804	Air Filter	1.00	13.97

Invoice Number I001504 **Date** 11/10/2021 **Mileage** 185982 **Job Value** 301.13

Vehicle Details MG8073E PA FORD E-450 SUPER DUTY SRT AMB. 2007

Labor	Value
Service call to Carlisle PD for no start, attempted to jump start vehicle but batteries were completely dead. Returned to shop for more tools and spare batteries. Went back to Carlisle PD and installed batteries and got vehicle to shop to further diagnose.	115.05
Charged old batteries to verify if they were still ok, found batteries to be good recharged and installed back into vehicle. Plug shore line in and verified power was making it through the cable, found 120v at connector. Plugged shore line into vehicle, checked power at inverter/battery tender found no voltage coming into charger. Chased wiring back into cab of vehicle to find GFI breaker had blown. Left vehicle sit over night to see if symptom would reoccur, no issues found at this time. Also fabricated handle for battery shut off switch on driver seat.	184.08

Parts		Qty	Value

Invoice Number I001422 **Date** 9/29/2021 **Mileage** 185827 **Job Value** 690.68

Vehicle Details MG8073E PA FORD E-450 SUPER DUTY SRT AMB. 2007

Labor	Value
Shop Labor- Cumberland County. Replaced muffler and exhaust front pipe. Had to fabricate exhaust to make work.	184.08
Shop Labor- Cumberland County. No a/c front or rear. Checked a/c system. Evacuated and recharged a/c and added dye. Front a/c working but rear will not get cold. Found rear vacuum switch bad for rear a/c heater control valve. Replaced rear a/c vacuum control switch that was bought by DA Dept. All is working now.	138.06
PM Service, Check Lights, Brakes and overall safety of vehicle	46.02
State Inspection	27.61

Parts		Qty	Value
CNVWWFliud Clearv	Windshield Washer Fluid	1.00	1.15
CNV84323	Oil Filter	1.00	14.34
CNV15W-40 PETRO	Oil	15.00	33.90
CNVMERCON LV FF	Mercon LV Automatic Trans. Fluid.	3.00	16.74
CNV2506	Muffler	1.00	161.76
CNV28812	Exhaust Pipe	1.00	17.96
CNVH312P	Exhaust Clamp	3.00	11.10
CNVH400	Exhaust Clamp	1.00	6.77
CNV8962	Exhaust Pipe Adapter	1.00	13.22
CNV11111 AZ	AC Oil Dye	2.00	3.98
CNVR134A AZ	Refrigerant Per Pound	3.00	9.99

Invoice Number I001329 **Date** 8/2/2021 **Mileage** 185735 **Job Value** 430.97

Vehicle Details MG8073E PA FORD E-450 SUPER DUTY SRT AMB. 2007

Labor	Value	Parts		Qty	Value
Shop Labor- Cumberland County. Battery door tore off. Took hinge off battery door and straightened hinge. Reattached hinge and battery door to van. Repaired battery tray that came apart.	115.05	CNVMTP-65 HD INTER	Interstate Battery	2.00	267.90
Shop Labor- Cumberland County. Checked batteries and charging system. Battery has a bad cell. Replaced both batteries and cleaned terminals.	46.02				

Invoice Number K10961 **Date** 10/9/2020 **Mileage** 185198 **Job Value** 622.07

Vehicle Details MG8073E PA FORD E-450 SUPER DUTY SRT AMB. 2007

Work Description State Inspection checked fluids and tire pressures.
Replaced exhaust tailpipe and elbow.
Replaced both front sway bar inner bushings
Checked power steering system. Flushed out ps system and added new fluid. Still stiff. Replaced power steering pump. Steers easy now.

Labor	Value	Parts		Qty	Value
State inspection	53.05	CNV42445 advance	3 inch elbow	1.00	23.19
tailpipe broken off	79.58	CNV17129 az	exhaust clamps	5.00	19.45
front sway bar bushings torn	53.05	CNV17582 az	exhaust connector	1.00	2.92
Power steering is stiff at idle.	190.98	CNVJBU1017 fisher	Sway Bar Bushing	1.00	8.62
		CNVMercon lv FF	Mercon LV Automatic Trans. Fluid.	5.00	27.90
		CNV7C2Z3 A674BRM family	Power Steering Pump	1.00	157.33