

Detailed services/breakdown

My company
 Wednesday, September 1, 2021
 10:51

Display criteria

Period : All

Vehicle(s) : Ford/Explorer/2016

Vehicle : 67-79 - Ford/Explorer/2016/MG3328J

Service : purchase and install of all lighting equipment (No used equipment was used (Service)				
Date :	9/3/2016	Technician responsible :	N/D	Cost : \$12,433.00
Reference :	IN000104030	Vendor responsible :	Metropolitan Communications	Odometer : 0
Type	Description	Qty.	Unit cost	Total cost
Other	Upfitting the complete vehicle with lighting	1.00	\$12,433.00	\$12,433.00
<i>Total service :</i>				\$12,433.00

Service : Install and wire scene light, mount and wirre rear hatch trim, and switch (Service)				
Date :	9/3/2016	Technician responsible :	N/D	Cost : \$412.70
Reference :	IN000104026	Vendor responsible :	Metropolitan Communications	Odometer : 0
Type	Description	Qty.	Unit cost	Total cost
Other	install scene light	1.00	\$412.70	\$412.70
<i>Total service :</i>				\$412.70

Service : Oil and filter change (Service)				
Date :	11/21/2016	Technician responsible :	N/D	Cost : \$39.95
Reference :	12407	Vendor responsible :	Thorntons Gulf	Odometer : 3,259
Type	Description	Qty.	Unit cost	Total cost
Other	Oil and filter change	1.00	\$39.95	\$39.95
<i>Total service :</i>				\$39.95

Service :	Install camera system, mirror mount, fuse holder. (Glue kit and tape) (Service)				
Date :	9/26/2016	Technician responsible :	N/D	Cost :	\$571.18
Reference :	A034658	Vendor responsible :	West Goshen Automotive	Odometer :	270
Type	Description	Qty.	Unit cost	Total cost	
Other	Install camera system, mirror mount, fuse holder	1.00	\$571.18	\$571.18	
				<i>Total service :</i>	\$571.18

Service :	replace fuel tank (Service)				
Date :	1/2/2017	Technician responsible :	N/D	Cost :	\$0.00
Reference :	1569	Vendor responsible :	Garnet Ford	Odometer :	5,374
Type	Description	Qty.	Unit cost	Total cost	
Other	replace fuel tank	1.00	\$0.00	\$0.00	
				<i>Total service :</i>	\$0.00

Service :	replace ignition cylinder housing assembly (Service)				
Date :	1/16/2017	Technician responsible :	N/D	Cost :	\$0.00
Reference :	16481	Vendor responsible :	Garnet Ford	Odometer :	6,027
Type	Description	Qty.	Unit cost	Total cost	
Other	replace ignition cylinder housing assembly	1.00	\$0.00	\$0.00	
				<i>Total service :</i>	\$0.00

Service :	State Insp. and Emission, Oil change (Service)				
Date :	3/8/2017	Technician responsible :	N/D	Cost :	\$113.50
Reference :	8336	Vendor responsible :	Thorntons Gulf	Odometer :	9,868
Type	Description	Qty.	Unit cost	Total cost	
Other	State Insp. and Emission, Oil change	1.00	\$113.50	\$113.50	
				<i>Total service :</i>	\$113.50

Service :	Oil and Filter Change (Service)					
Date :	6/20/2017	Technician responsible :	N/D	Cost :	\$39.50	
Reference :	8061	Vendor responsible :	Thorntons Gulf	Odometer :	16,638	
Type	Description			Qty.	Unit cost	Total cost
Other	Oil and Filter Change			1.00	\$39.50	\$39.50
					<i>Total service :</i>	\$39.50

Service :	Remove and replce Spot light (Service)					
Date :	6/17/2017	Technician responsible :	N/D	Cost :	\$87.00	
Reference :	IN000105790	Vendor responsible :	Metropolitan Communications	Odometer :	0	
Type	Description			Qty.	Unit cost	Total cost
Other	Remove and replce Spot light			1.00	\$87.00	\$87.00
					<i>Total service :</i>	\$87.00

Service :	Change and balance 4 tires (Dispose of old tires) (Service)					
Date :	7/13/2017	Technician responsible :	N/D	Cost :	\$96.00	
Reference :	11314	Vendor responsible :	Thorntons Gulf	Odometer :	17,941	
Type	Description			Qty.	Unit cost	Total cost
Other	change and balance 4 tires			1.00	\$96.00	\$96.00
					<i>Total service :</i>	\$96.00

Service :	oil and filter change (Service)					
Date :	8/16/2017	Technician responsible :	N/D	Cost :	\$39.50	
Reference :	7209	Vendor responsible :	Thorntons Gulf	Odometer :	19,914	
Type	Description			Qty.	Unit cost	Total cost
Other	oil and filter change			1.00	\$39.50	\$39.50
					<i>Total service :</i>	\$39.50

Service : Oil and Filter Change (Service)				
Date :	9/25/2017	Technician responsible :	N/D	Cost : \$39.50
Reference :	10767	Vendor responsible :	Thorntons Gulf	Odometer : 22,729
Type	Description	Qty.	Unit cost	Total cost
Other	Oil and Filter Change	1.00	\$39.50	\$39.50
<i>Total service :</i>				\$39.50

Service : Reprogram power steering module, reseal all areas for exhaust recall (Service)				
Date :	10/24/2017	Technician responsible :	N/D	Cost : \$0.00
Reference :	32721	Vendor responsible :	Garnet Ford	Odometer : 24,381
Type	Description	Qty.	Unit cost	Total cost
Other	Reprogram power steering module, reseal all areas for exhaust recall	1.00	\$0.00	\$0.00
<i>Total service :</i>				\$0.00

Service : Replace Battery (Service)				
Date :	11/18/2017	Technician responsible :	N/D	Cost : \$150.00
Reference :	7058	Vendor responsible :	Thorntons Gulf	Odometer : 25,677
Type	Description	Qty.	Unit cost	Total cost
Other	Replace Battery	1.00	\$150.00	\$150.00
<i>Total service :</i>				\$150.00

Service : Replace front brakes and 2 front rotors (Service)				
Date :	11/21/2017	Technician responsible :	N/D	Cost : \$335.00
Reference :	7066	Vendor responsible :	Thorntons Gulf	Odometer : 26,019
Type	Description	Qty.	Unit cost	Total cost
Other	Replace front brakes and 2 front rotors	1.00	\$335.00	\$335.00
<i>Total service :</i>				\$335.00

Service : Oil and Filter change (Service)				
Date :	11/20/2017	Technician responsible :	N/D	Cost : \$39.50
Reference :	7064	Vendor responsible :	Thorntons Gulf	Odometer : 25,911
Type	Description	Qty.	Unit cost	Total cost
Other	oil and filter change	1.00	\$39.50	\$39.50
<i>Total service :</i>				\$39.50

Service : Replace left side turbo assembly, replace spark plugs (Service)				
Date :	11/27/2017	Technician responsible :	N/D	Cost : \$0.00
Reference :	W37250	Vendor responsible :	Pacifico Marple Ford	Odometer : 26,465
Type	Description	Qty.	Unit cost	Total cost
Other	Replace left side turbo assembly, replace spark plugs	1.00	\$0.00	\$0.00
<i>Total service :</i>				\$0.00

Service : Adjustment to the" under body shield" which was rubbing against the Y-Pipe (Service)				
Date :	1/3/2018	Technician responsible :	N/D	Cost : \$116.50
Reference :	C38700	Vendor responsible :	Pacifico Marple Ford	Odometer : 28,162
Type	Description	Qty.	Unit cost	Total cost
Other	Adjustment to the" under body shield" which was rubbing against the Y-Pipe	1.00	\$116.50	\$116.50
<i>Total service :</i>				\$116.50

Service : Oil and Filter Change (Service)				
Date :	1/16/2018	Technician responsible :	N/D	Cost : \$39.50
Reference :	11962	Vendor responsible :	Thorntons Gulf	Odometer : 29,094
Type	Description	Qty.	Unit cost	Total cost
Other	Oil and Filter Change	1.00	\$39.50	\$39.50
<i>Total service :</i>				\$39.50

Service : Replace Wiper Blades (Service)				
Date :	1/25/2018	Technician responsible :	N/D	Cost : \$49.00
Reference :	11994	Vendor responsible :	Thorntons Gulf	Odometer : 29,901
Type	Description	Qty.	Unit cost	Total cost
Other	Replace Wiper Blades	1.00	\$49.00	\$49.00
<i>Total service :</i>				\$49.00

Service : Emission and State Inspection (Service)				
Date :	3/8/2018	Technician responsible :	N/D	Cost : \$75.00
Reference :	13281	Vendor responsible :	Thorntons Gulf	Odometer : 32,506
Type	Description	Qty.	Unit cost	Total cost
Other	Emission and State Inspection	1.00	\$75.00	\$75.00
<i>Total service :</i>				\$75.00

Service : Oil and Filter Change (Service)				
Date :	3/17/2018	Technician responsible :	N/D	Cost : \$44.95
Reference :	13303	Vendor responsible :	Thorntons Gulf	Odometer : 33,013
Type	Description	Qty.	Unit cost	Total cost
Other	Oil and Filter Change	1.00	\$44.95	\$44.95
<i>Total service :</i>				\$44.95

Service : Replace left side lower arm, side Axel and Left Rim. Front end alignment (Service)				
Date :	3/26/2018	Technician responsible :	N/D	Cost : \$862.00
Reference :	13347	Vendor responsible :	Thorntons Gulf	Odometer : 33,670
Type	Description	Qty.	Unit cost	Total cost
Other	Replace left side lower arm, side Axel and Left Rim. Front end alignment	1.00	\$862.00	\$862.00
<i>Total service :</i>				\$862.00

Service :	Oil and Filter Change (Service)			
Date :	5/7/2018	Technician responsible :	N/D	Cost : \$44.95
Reference :	13726	Vendor responsible :	Thorntons Gulf	Odometer : 35,961
Type	Description	Qty.	Unit cost	Total cost
Other	Oil and Filter Change	1.00	\$44.95	\$44.95
<i>Total service :</i>				\$44.95

Service :	Replace Driver Side Wheel bearing (Service)			
Date :	6/14/2018	Technician responsible :	N/D	Cost : \$284.00
Reference :	12821	Vendor responsible :	Thorntons Gulf	Odometer : 38,132
Type	Description	Qty.	Unit cost	Total cost
Other	Replace Driver Side Wheel bearing	1.00	\$284.00	\$284.00
<i>Total service :</i>				\$284.00

Service :	Oil and Filter Change (Service)			
Date :	6/27/2018	Technician responsible :	N/D	Cost : \$44.95
Reference :	13022	Vendor responsible :	Thorntons Gulf	Odometer : 39,664
Type	Description	Qty.	Unit cost	Total cost
Other	oil and filter change	1.00	\$44.95	\$44.95
<i>Total service :</i>				\$44.95

Service :	Mount and Balance 2 Tires (Service)			
Date :	7/26/2018	Technician responsible :	N/D	Cost : \$48.00
Reference :	13077	Vendor responsible :	Thorntons Gulf	Odometer : 40,602
Type	Description	Qty.	Unit cost	Total cost
Other	Mount and Balance 2 Tires	1.00	\$48.00	\$48.00
<i>Total service :</i>				\$48.00

Service : Oil and Filter Change (Service)				
Date :	8/31/2018	Technician responsible :	N/D	Cost : \$44.95
Reference :	13105	Vendor responsible :	Thorntons Gulf	Odometer : 42,748
Type	Description	Qty.	Unit cost	Total cost
Other	Oil and Filter Change	1.00	\$44.95	\$44.95
<i>Total service :</i>				\$44.95

Service : Replace Front and rear Brakes and Rotors, (Service)				
Date :	10/1/2018	Technician responsible :	N/D	Cost : \$590.00
Reference :	11036	Vendor responsible :	Thorntons Gulf	Odometer : 44,206
Type	Description	Qty.	Unit cost	Total cost
Other	Replace Front and rear Brakes and Rotors,	1.00	\$590.00	\$590.00
<i>Total service :</i>				\$590.00

Service : Oil and Filter Change (Service)				
Date :	10/23/2018	Technician responsible :	N/D	Cost : \$44.95
Reference :	12032	Vendor responsible :	Thorntons Gulf	Odometer : 45,680
Type	Description	Qty.	Unit cost	Total cost
Other	Oil and Filter Change	1.00	\$44.95	\$44.95
<i>Total service :</i>				\$44.95

Service : Replce all Spark Plugs and Boots (Service)				
Date :	11/7/2018	Technician responsible :	N/D	Cost : \$536.48
Reference :	C51163	Vendor responsible :	Pacifico Marple Ford	Odometer : 46,633
Type	Description	Qty.	Unit cost	Total cost
Other	Replce all Spark Plugs and Boots	1.00	\$536.48	\$536.48
<i>Total service :</i>				\$536.48

Service : Replace Rear Suspension Toe Link, Alignment (Service)				
Date :	11/7/2018	Technician responsible :	N/D	Cost : \$207.12
Reference :	W51163	Vendor responsible :	Pacifico Marple Ford	Odometer : 46,633
Type	Description	Qty.	Unit cost	Total cost
Other	Replace Rear Suspension Toe Link, Alignment	1.00	\$207.12	\$207.12
<i>Total service :</i>				\$207.12

Service : Oil and Filter Change (Service)				
Date :	12/7/2018	Technician responsible :	N/D	Cost : \$44.95
Reference :	7484	Vendor responsible :	Thorntons Gulf	Odometer : 48,501
Type	Description	Qty.	Unit cost	Total cost
Other	Oil and Filter Change	1.00	\$44.95	\$44.95
<i>Total service :</i>				\$44.95

Service : Replace Bank 1 02 Sensor (Service)				
Date :	12/20/2018	Technician responsible :	N/D	Cost : \$346.90
Reference :	C52879	Vendor responsible :	Pacifico Marple Ford	Odometer : 49,264
Type	Description	Qty.	Unit cost	Total cost
Other	Replace Bank 1 02 Sensor	1.00	\$346.90	\$346.90
<i>Total service :</i>				\$346.90

Service : Emission and State Inspection (Service)				
Date :	2/13/2019	Technician responsible :	N/D	Cost : \$75.00
Reference :	8710	Vendor responsible :	Thorntons Gulf	Odometer : 53,327
Type	Description	Qty.	Unit cost	Total cost
Other	Emission and State Inspection	1.00	\$75.00	\$75.00
<i>Total service :</i>				\$75.00

Service : Oil and Filter Change (Service)					
Date :	2/12/2019	Technician responsible :	N/D	Cost :	\$44.95
Reference :	8705	Vendor responsible :	Thorntons Gulf	Odometer :	52,165
Type	Description	Qty.	Unit cost	Total cost	
Other	Oil and Filter Change	1.00	\$44.95	\$44.95	
				<i>Total service :</i>	\$44.95

Service : Oil and Filter Change (Service)					
Date :	4/2/2019	Technician responsible :	N/D	Cost :	\$44.95
Reference :	14601	Vendor responsible :	Thorntons Gulf	Odometer :	55,534
Type	Description	Qty.	Unit cost	Total cost	
Other	Oil and Filter Change,	1.00	\$44.95	\$44.95	
				<i>Total service :</i>	\$44.95

Service : Replace Rear Lower Cover and Valance (Bumper area) (Service)					
Date :	5/6/2019	Technician responsible :	N/D	Cost :	\$681.34
Reference :	CHCB27673	Vendor responsible :	Videon Dodge	Odometer :	57,845
Type	Description	Qty.	Unit cost	Total cost	
Other	Replace Rear Lower Cover and Valance (Bumper area)	1.00	\$681.34	\$681.34	
				<i>Total service :</i>	\$681.34

Service : Replace Air Filter, Replace Sensor on Low Side fuel Mount on Fuel Tan. (Service)					
Date :	5/15/2019	Technician responsible :	N/D	Cost :	\$744.16
Reference :	C58961	Vendor responsible :	Pacifico Marple Ford	Odometer :	57,845
Type	Description	Qty.	Unit cost	Total cost	
Other	Replace Air Filter, Replace Sensor on Low Side fuel Mount on Fuel Tan.	1.00	\$744.16	\$744.16	
				<i>Total service :</i>	\$744.16

Service :	Oil and Filter Change, Replace Molding for the Pass Side Window area (Service)				
Date :	6/18/2019	Technician responsible :	N/D	Cost :	\$192.95
Reference :	13886	Vendor responsible :	Thorntons Gulf	Odometer :	58,583
Type	Description	Qty.	Unit cost	Total cost	
Other	Oil and Filter Change, Replace Molding for the Pass Side Window area	1.00	\$192.95	\$192.95	
				<i>Total service :</i>	\$192.95

Service :	Replce Low Fuel Pressure Sensor (Service)				
Date :	7/30/2019	Technician responsible :	N/D	Cost :	\$649.73
Reference :	C70558	Vendor responsible :	Garnet Ford	Odometer :	59,616
Type	Description	Qty.	Unit cost	Total cost	
Other	Replce Low Fuel Pressure Sensor	1.00	\$649.73	\$649.73	
				<i>Total service :</i>	\$649.73

Service :	Diagnostic Check as a result of a check engine light (Service)				
Date :	8/23/2019	Technician responsible :	N/D	Cost :	\$374.95
Reference :	C71631	Vendor responsible :	Garnet Ford	Odometer :	60,256
Type	Description	Qty.	Unit cost	Total cost	
Other	Diagnostic Check as a result of a check engine light	1.00	\$374.95	\$374.95	
				<i>Total service :</i>	\$374.95

Service :	Replaced Throttle Body (Service)				
Date :	10/7/2019	Technician responsible :	N/D	Cost :	\$407.41
Reference :	C74785	Vendor responsible :	Garnet Ford	Odometer :	61,402
Type	Description	Qty.	Unit cost	Total cost	
Other	Replaced Throttle Body	1.00	\$407.41	\$407.41	
				<i>Total service :</i>	\$407.41

Service :	Oil and Filter Change (Service)				
Date :	10/22/2019	Technician responsible :	N/D	Cost :	\$44.95
Reference :	15051	Vendor responsible :	Thorntons Gulf	Odometer :	61,802
Type	Description	Qty.	Unit cost	Total cost	
Other	Oil and Filter Change	1.00	\$44.95	\$44.95	
				<i>Total service :</i>	\$44.95

Service :	Replaced Fuel Driver Module, Oil and Filter Change, (Service)				
Date :	11/1/2019	Technician responsible :	N/D	Cost :	\$372.98
Reference :	6108554/1	Vendor responsible :	Matthews Paoli Ford	Odometer :	61,849
Type	Description	Qty.	Unit cost	Total cost	
Other	Replaced Fuel Driver Module, Oil and Filter Change,	1.00	\$372.98	\$372.98	
				<i>Total service :</i>	\$372.98

Service :	Mount and Balance 4 Tires (Service)				
Date :	11/6/2019	Technician responsible :	N/D	Cost :	\$100.00
Reference :	14774	Vendor responsible :	Thorntons Gulf	Odometer :	61,950
Type	Description	Qty.	Unit cost	Total cost	
Other	Mount and Balance 4 Tires	1.00	\$100.00	\$100.00	
				<i>Total service :</i>	\$100.00

Service :	Replace Sender and Pump Assembly, Gasket, Sensor, Replace Fuel Vapor Cannister, Replace Fuel Pump, Replace O2 Sensor, Replace Fuel Injector Assembly, Replace Spark Plugs. Replace Gaskets A, BA, D (Service)				
Date :	2/5/2020	Technician responsible :	N/D	Cost :	\$1,094.05
Reference :	6110307	Vendor responsible :	Matthews Paoli Ford	Odometer :	63,084
Type	Description	Qty.	Unit cost	Total cost	
Other	Replace Sender and Pump Assembly, Gasket, Sensor, Replace Fuel Vapor Cannister, Replace Fuel Pump, Replace O2 Sensor, Replace Fuel Injector	1.00	\$1,094.05	\$1,094.05	

Total service : \$1,094.05

Service : Emission and State Inspection, Upper Engine Induction System Cleaning (Service)					
Date :	3/27/2020	Technician responsible :	N/D	Cost :	\$474.82
Reference :	6112118/1	Vendor responsible :	Matthews Paoli Ford	Odometer :	65,771
Type	Description	Qty.	Unit cost	Total cost	
Other	Emission and State Inspection, Upper Engine Induction System Cleaning	1.00	\$474.82	\$474.82	
<i>Total service :</i>					\$474.82

Service : Oil and Filter Change (Service)					
Date :	4/30/2020	Technician responsible :	N/D	Cost :	\$44.95
Reference :	15920	Vendor responsible :	Thorntons Gulf	Odometer :	68,270
Type	Description	Qty.	Unit cost	Total cost	
Other	Oil and Filter Change	1.00	\$44.95	\$44.95	
<i>Total service :</i>					\$44.95

Service : Replace Front Brakes and Rotors (Service)					
Date :	5/8/2020	Technician responsible :	N/D	Cost :	\$335.00
Reference :	15939	Vendor responsible :	Thorntons Gulf	Odometer :	68,493
Type	Description	Qty.	Unit cost	Total cost	
Other	Replace Front Brakes and Rotors	1.00	\$335.00	\$335.00	
<i>Total service :</i>					\$335.00

Service : Oil and Filter Change (Service)					
Date :	6/24/2020	Technician responsible :	N/D	Cost :	\$44.95
Reference :	16359	Vendor responsible :	Thorntons Gulf	Odometer :	71,458
Type	Description	Qty.	Unit cost	Total cost	

Other	Oil and Filter Change	1.00	\$44.95	\$44.95
			<i>Total service :</i>	\$44.95

Service : Paint and refinish Hood (Service)				
Date :	10/21/2020	Technician responsible :	N/D	Cost : \$342.72
Reference :	CHCB53571	Vendor responsible :	Videon Dodge	Odometer : 0
Type	Description	Qty.	Unit cost	Total cost
Other	Paint and Refinish Hood	1.00	\$342.72	\$342.72
			<i>Total service :</i>	\$342.72

Service : Oil and Filter Change (Service)				
Date :	11/11/2020	Technician responsible :	N/D	Cost : \$44.95
Reference :	15554	Vendor responsible :	Thorntons Gulf	Odometer : 75,236
Type	Description	Qty.	Unit cost	Total cost
Other	Oil and Filter Change	1.00	\$44.95	\$44.95
			<i>Total service :</i>	\$44.95

Service : Replace Wiper Blades (Service)				
Date :	10/28/2020	Technician responsible :	N/D	Cost : \$58.00
Reference :	14946	Vendor responsible :	Thorntons Gulf	Odometer : 0
Type	Description	Qty.	Unit cost	Total cost
Other	Replace Wiper Blades	1.00	\$58.00	\$58.00
			<i>Total service :</i>	\$58.00

Service : Rear Brakes, Replace 2 rear rotors (Service)				
Date :	2/23/2021	Technician responsible :	N/D	Cost : \$325.00
Reference :	17138	Vendor responsible :	Thorntons Gulf	Odometer : 78,274
Type	Description	Qty.	Unit cost	Total cost

Other	Rear Brakes, Replace 2 rear rotors	1.00	\$325.00	\$325.00
			<i>Total service :</i>	\$325.00

Service : Replace Coil Asy, Ignition, Spark Plug, Roller Tappet, Pump Assembly- Fuel, Sea Foam Injector Cleaner, Replace Rear Toe Link, Emission and State Inspection (Service)				
Date :	3/22/2021	Technician responsible :	N/D	Cost : \$1,415.31
Reference :	6120416/1	Vendor responsible :	Matthews Paoli Ford	Odometer : 78,737
Type	Description	Qty.	Unit cost	Total cost
Other	Replace Coil Asy, Ignition, Spark Plug, Roller Tappet, Pump Assembly- Fuel, Sea Foam Injector Cleaner, Replace Rear Toe Link, Emission and State Inspection	1.00	\$1,415.31	\$1,415.31
			<i>Total service :</i>	\$1,415.31

Service : Oil and Filter Change (Service)				
Date :	4/29/2021	Technician responsible :	N/D	Cost : \$44.95
Reference :	16831	Vendor responsible :	Thorntons Gulf	Odometer : 79,189
Type	Description	Qty.	Unit cost	Total cost
Other	Oil and Filter Change	1.00	\$44.95	\$44.95
			<i>Total service :</i>	\$44.95

Total of the vehicle : \$25,778.60