# *Detailed services/breakdown*



Display criteria
Period : All
Vehicle(s) : Dodge/Durango/2019

## *Vehicle : 67-91 - Dodge/Durango/2019/MG3153L*

**Service :** Complete Upfitting of new Patrol Vehicle (Service )

**Date :** 5/9/2019 **Technician responsible :** N/D **Cost :** $14,205.00
**Reference :** IN000109063 **Vendor responsible :** Metropolitan Communications **Odometer :** 1

| Type | Description | Qty. | Unit cost | Total cost |
|---|---|---|---|---|
| Other | Complete Upfitting of new Patrol Vehicle | 1.00 | $14,205.00 | $14,205.00 |
| | | *Total service :* | | $14,205.00 |

**Service :** Oil and Filter Change (Service )

**Date :** 6/19/2019 **Technician responsible :** N/D **Cost :** $44.95
**Reference :** 13892 **Vendor responsible :** Thorntons Gulf **Odometer :** 2,998

| Type | Description | Qty. | Unit cost | Total cost |
|---|---|---|---|---|
| Other | Oil and Filter Change | 1.00 | $44.95 | $44.95 |
| | | *Total service :* | | $44.95 |

**Service :** Oil and Filter Change (Service )

**Date :** 8/2/2019 **Technician responsible :** N/D **Cost :** $44.95
**Reference :** 14242 **Vendor responsible :** Thorntons Gulf **Odometer :** 5,979

| Type | Description | Qty. | Unit cost | Total cost |
|---|---|---|---|---|
| Other | Oil and Filter Change | 1.00 | $44.95 | $44.95 |
| | | *Total service :* | | $44.95 |

**Service :** Oil and Filter Change (Service )

**Date :** 9/10/2019 **Technician responsible :** N/D **Cost :** $44.95

**Reference :** 14044 **Vendor responsible :** Thorntons Gulf **Odometer :** 9,065

| Type | Description | Qty. | Unit cost | Total cost |
|---|---|---|---|---|
| Other | Oil and Filter Change | 1.00 | $44.95 | $44.95 |
| | | | *Total service :* | $44.95 |

**Service :** Oil and Filter Change (Service )

**Date :** 10/22/2019 **Technician responsible :** N/D **Cost :** $44.95

**Reference :** 15052 **Vendor responsible :** Thorntons Gulf **Odometer :** 11,895

| Type | Description | Qty. | Unit cost | Total cost |
|---|---|---|---|---|
| Other | Oil and Filter Change | 1.00 | $44.95 | $44.95 |
| | | | *Total service :* | $44.95 |

**Service :** Replace A/C Condensor and Recharge Freon (Service )

**Date :** 10/25/2019 **Technician responsible :** N/D **Cost :** $0.00

**Reference :** CHCS38120 **Vendor responsible :** Videon Dodge **Odometer :** 12,100

| Type | Description | Qty. | Unit cost | Total cost |
|---|---|---|---|---|
| Other | Replace A/C Condensor and Recharge Freon | 1.00 | $0.00 | $0.00 |
| | | | *Total service :* | $0.00 |

**Service :** Replace Wiper Blades (Service )

**Date :** 10/31/2019 **Technician responsible :** N/D **Cost :** $28.00

**Reference :** 14752 **Vendor responsible :** Thorntons Gulf **Odometer :** 12,392

| Type | Description | Qty. | Unit cost | Total cost |
|---|---|---|---|---|
| Other | Replace Wiper Blades | 1.00 | $28.00 | $28.00 |
| | | | *Total service :* | $28.00 |

**Service :** Replace Oil Cooler, Thermostat, and Radiator Cap, Flush cooling System and Remove and replace leaking oil Filter (Service )

**Date :** 12/3/2019 **Technician responsible :** N/D **Cost :** $12.25
**Reference :** CHCS39758 **Vendor responsible :** Videon Dodge **Odometer :** 14,397

| Type | Description | Qty. | Unit cost | Total cost |
|---|---|---|---|---|
| Other | Replace Oil Cooler, Thermostat, and Radiator Cap, Flush cooling System and Remove and replace leaking oil Filter | 1.00 | $12.25 | $12.25 |

*Total service :* $12.25

**Service :** Mount and Balance 2 tires (Service )

**Date :** 12/9/2019 **Technician responsible :** N/D **Cost :** $50.00
**Reference :** 15260 **Vendor responsible :** Thorntons Gulf **Odometer :** 14,838

| Type | Description | Qty. | Unit cost | Total cost |
|---|---|---|---|---|
| Other | Mount and Balance 2 tires | 1.00 | $50.00 | $50.00 |

*Total service :* $50.00

**Service :** Replace Right front headlight assembly. (This was Covered Under Warranty) Removing and reinstalling the pushbumper was not covered. This was where the charge occurred. (Service )

**Date :** 12/12/2019 **Technician responsible :** N/D **Cost :** $330.00
**Reference :** CHCS40470 **Vendor responsible :** Videon Dodge **Odometer :** 14,998

| Type | Description | Qty. | Unit cost | Total cost |
|---|---|---|---|---|
| Other | Replace Head Light | 1.00 | $330.00 | $330.00 |

*Total service :* $330.00

**Service :** Replace Left front headlight assembly. (This was Covered Under Warranty) Removing and reinstalling the pushbumper was not. This was where the charge occurred. (Service )

**Date :** 1/17/2020 **Technician responsible :** N/D **Cost :** $325.00
**Reference :** CHCS42268 **Vendor responsible :** Videon Dodge **Odometer :** 16,886

| Type | Description | Qty. | Unit cost | Total cost |
|---|---|---|---|---|

| | | | | |
|---|---|---|---|---|
| Other | Replace Left front headlight assembly. | 1.00 | $325.00 | $325.00 |
| | | | *Total service :* | $325.00 |

**Service :** Replace Front Brakes. (Service )

**Date :** 2/3/2020 **Technician responsible :** N/D **Cost :** $165.00

**Reference :** 16261 **Vendor responsible :** Thorntons Gulf **Odometer :** 17,687

| Type | Description | Qty. | Unit cost | Total cost |
|---|---|---|---|---|
| Other | Replace Front Brakes. | 1.00 | $165.00 | $165.00 |
| | | | *Total service :* | $165.00 |

**Service :** Replace the Condenser & Recharge Freon (Service )

**Date :** 2/26/2020 **Technician responsible :** N/D **Cost :** $1,044.94

**Reference :** CHCS44198 **Vendor responsible :** Videon Dodge **Odometer :** 18,652

| Type | Description | Qty. | Unit cost | Total cost |
|---|---|---|---|---|
| Other | Replace the Condenser & Recharge Freon | 1.00 | $1,044.94 | $1,044.94 |
| | | | *Total service :* | $1,044.94 |

**Service :** Emission and State Inspection, Oil and Filter Change (Service )

**Date :** 3/5/2020 **Technician responsible :** N/D **Cost :** $120.95

**Reference :** 15831 **Vendor responsible :** Thorntons Gulf **Odometer :** 19,194

| Type | Description | Qty. | Unit cost | Total cost |
|---|---|---|---|---|
| Other | Emission and State Inspection, Oil and Filter Change | 1.00 | $120.95 | $120.95 |
| | | | *Total service :* | $120.95 |

**Service :** Oil and Filter Change (Service )

**Date :** 5/8/2020 **Technician responsible :** N/D **Cost :** $44.95

**Reference :** 15938 **Vendor responsible :** Thorntons Gulf **Odometer :** 22,555

| Type | Description | Qty. | Unit cost | Total cost |
|---|---|---|---|---|

| | | | | |
|---|---|---|---|---|
| Other | Oil and Filter Change | 1.00 | $44.95 | $44.95 |
| | | | *Total service :* | $44.95 |

**Service :** Oil and Filter Change (Service )

**Date :** 7/9/2020 **Technician responsible :** N/D **Cost :** $44.95

**Reference :** 16436 **Vendor responsible :** Thorntons Gulf **Odometer :** 25,905

| Type | Description | Qty. | Unit cost | Total cost |
|---|---|---|---|---|
| Other | Oil and Filter Change | 1.00 | $44.95 | $44.95 |
| | | *Total service :* | | $44.95 |

**Service :** Replace A/C Condenser and Recharge System Banks. (Service )

**Date :** 8/10/2020 **Technician responsible :** N/D **Cost :** $65.00

**Reference :** CHCS51042 **Vendor responsible :** Videon Dodge **Odometer :** 27,377

| Type | Description | Qty. | Unit cost | Total cost |
|---|---|---|---|---|
| Other | Replace A/C Condenser and Recharge System Banks. | 1.00 | $65.00 | $65.00 |
| | | *Total service :* | | $65.00 |

**Service :** Replace Left Motor Mount, Replace Insulator (Service )

**Date :** 9/18/2020 **Technician responsible :** N/D **Cost :** $0.00

**Reference :** CHCS53081 **Vendor responsible :** Videon Dodge **Odometer :** 28,664

| Type | Description | Qty. | Unit cost | Total cost |
|---|---|---|---|---|
| Other | Replace Left Motor Mount, Replace Insulator | 1.00 | $0.00 | $0.00 |
| | | *Total service :* | | $0.00 |

**Service :** Replace Water Pump (Service )

**Date :** 10/16/2020 **Technician responsible :** N/D **Cost :** $0.00

**Reference :** CHCS54460 **Vendor responsible :** Videon Dodge **Odometer :** 29,381

| Type | Description | Qty. | Unit cost | Total cost |
|---|---|---|---|---|

| | | | | |
|---|---|---|---|---|
| Other | Replace Water Pump | 1.00 | $0.00 | $0.00 |
| | | | *Total service :* | $0.00 |

**Service :** Oil and Filter Change, Mount and Balance 2 tires (Service )

**Date :** 10/14/2020 **Technician responsible :** N/D **Cost :** $98.95

**Reference :** 15394 **Vendor responsible :** Thorntons Gulf **Odometer :** 29,366

| Type | Description | Qty. | Unit cost | Total cost |
|---|---|---|---|---|
| Other | Oil and Filter Change, Mount and balance 2 tires | 1.00 | $98.95 | $98.95 |
| | | | *Total service :* | $98.95 |

**Service :** Tightened terminals and sockets on the drivers side headlamp (Service )

**Date :** 1/4/2021 **Technician responsible :** N/D **Cost :** $65.25

**Reference :** CHCS57959 **Vendor responsible :** Videon Dodge **Odometer :** 33,484

| Type | Description | Qty. | Unit cost | Total cost |
|---|---|---|---|---|
| Other | Tightened terminals and sockets on the drivers side headlamp | 1.00 | $65.25 | $65.25 |
| | | | *Total service :* | $65.25 |

**Service :** Oil and Filter Change (Service )

**Date :** 12/28/2020 **Technician responsible :** N/D **Cost :** $44.95

**Reference :** 15666 **Vendor responsible :** Thorntons Gulf **Odometer :** 33,192

| Type | Description | Qty. | Unit cost | Total cost |
|---|---|---|---|---|
| Other | Oil and Filter Change | 1.00 | $44.95 | $44.95 |
| | | | *Total service :* | $44.95 |

**Service :** Replace Engine Long Block Assembly, All Seals & Gaskets, Replace Oil Filter and Coolant, Replace Battery, Replace Radiator Drain, Replace Idler Pulley & Oil Cooler (Service )

**Date :** 3/25/2021 **Technician responsible :** N/D **Cost :** $619.74

**Reference :** CHCS61042 **Vendor responsible :** Videon Dodge **Odometer :** 37,168

| Type | Description | Qty. | Unit cost | Total cost |
|---|---|---|---|---|
| Other | Replace Engine Long Block Assembly, All Seals & Gaskets, Replace Oil Filter and Coolant, Replace Battery, Replace Radiator Drain, Replace Idler Pulley & Oil Cooler | 1.00 | $619.74 | $619.74 |
| | | | *Total service :* | $619.74 |

**Service :** Emission and State Insp., Mount and Balance 2 Tires, Replace Front Brakes, Alignment (Service )

**Date :** 4/16/2021 **Technician responsible :** N/D **Cost :** $380.00

**Reference :** 16974 **Vendor responsible :** Thorntons Gulf **Odometer :** 37,968

| Type | Description | Qty. | Unit cost | Total cost |
|---|---|---|---|---|
| Other | Emission and State Insp., Mount and Balance 2 Tires, Replace Front Brakes, Alignment | 1.00 | $380.00 | $380.00 |
| | | | *Total service :* | $380.00 |

**Service :** Repaired front end damage (Service )

**Date :** 6/28/2021 **Technician responsible :** N/D **Cost :** $4,745.45

**Reference :** CHCB65034 **Vendor responsible :** Videon Dodge **Odometer :** 41,604

| Type | Description | Qty. | Unit cost | Total cost |
|---|---|---|---|---|
| Other | Repaired front end damage | 1.00 | $4,745.45 | $4,745.45 |
| | | | *Total service :* | $4,745.45 |

**Service :** Replace Heater Tube Assembly, Fill and Bleed the cooling System (Service )

**Date :** 8/18/2021 **Technician responsible :** N/D **Cost :** $611.01

**Reference :** CHCS68373 **Vendor responsible :** Videon Dodge **Odometer :** 42,513

| Type | Description | Qty. | Unit cost | Total cost |
|---|---|---|---|---|
| Other | Replace Heater Tube Assembly, Fill and Bleed the cooling System | 1.00 | $611.01 | $611.01 |
| | | | *Total service :* | $611.01 |

**Service :** Oil and Filter Change (Service )

**Date :** 8/12/2021 **Technician responsible :** N/D **Cost :** $60.00

**Reference :** 17697 **Vendor responsible :** Thorntons Gulf **Odometer :** 42,303

| Type | Description | Qty. | Unit cost | Total cost |
|---|---|---|---|---|
| Other | Oil and Filter Change | 1.00 | $60.00 | $60.00 |

*Total service :* $60.00

**Service :** Replace AC blower motor, resister and fuse (Service )

**Date :** 10/21/2021 **Technician responsible :** N/D **Cost :** $628.83

**Reference :** CHCS71524 **Vendor responsible :** Videon Dodge **Odometer :** 44,995

| Type | Description | Qty. | Unit cost | Total cost |
|---|---|---|---|---|
| Other | Replace AC blower motor, resister and fuse | 1.00 | $628.83 | $628.83 |

*Total service :* $628.83

**Service :** Repaire and Replace left bank down stream oxygen sensor (AC Check) (Service )

**Date :** 10/20/2021 **Technician responsible :** N/D **Cost :** $360.19

**Reference :** CHCS71394 **Vendor responsible :** Videon Dodge **Odometer :** 44,950

| Type | Description | Qty. | Unit cost | Total cost |
|---|---|---|---|---|
| Other | Repaire and Replace left bank down stream oxygen sensor (AC Check) | 1.00 | $360.19 | $360.19 |

*Total service :* $360.19

**Service :** Oil and Filter Change (Service )

**Date :** 11/4/2021 **Technician responsible :** N/D **Cost :** $60.00

**Reference :** 18628 **Vendor responsible :** Thorntons Gulf **Odometer :** 45,614

| Type | Description | Qty. | Unit cost | Total cost |
|---|---|---|---|---|
| Other | Oil and Filter Change | 1.00 | $60.00 | $60.00 |

*Total service :* $60.00

**Service :** Repair Oxygen Sensor wiring connector (Service )

**Date :** 12/3/2021 **Technician responsible :** N/D **Cost :** $0.00

**Reference :** CHCS73314 **Vendor responsible :** Videon Dodge **Odometer :** 46,703

| Type | Description | Qty. | Unit cost | Total cost |
|---|---|---|---|---|
| Other | Repair Oxygen Sensor wiring connector | 1.00 | $0.00 | $0.00 |

*Total service :* $0.00

**Service :** Replace Left Front Headlight (Service )

**Date :** 11/18/2021 **Technician responsible :** N/D **Cost :** $35.00

**Reference :** 17486 **Vendor responsible :** Thorntons Gulf **Odometer :** 0

| Type | Description | Qty. | Unit cost | Total cost |
|---|---|---|---|---|
| Other | Replace Left Headlight | 1.00 | $35.00 | $35.00 |

*Total service :* $35.00

**Service :** Replace Oil Pressure Switch (Service )

**Date :** 1/18/2022 **Technician responsible :** N/D **Cost :** $0.00

**Reference :** CHCS75513 **Vendor responsible :** Videon Dodge **Odometer :** 48,108

| Type | Description | Qty. | Unit cost | Total cost |
|---|---|---|---|---|
| Other | Replace Oil Pressure Switch | 1.00 | $0.00 | $0.00 |

*Total service :* $0.00

**Service :** Oil and Filter Change (Service )

**Date :** 2/23/2022 **Technician responsible :** N/D **Cost :** $60.00

**Reference :** 17825 **Vendor responsible :** Thorntons Gulf **Odometer :** 49,097

| Type | Description | Qty. | Unit cost | Total cost |
|---|---|---|---|---|
| Other | Oil and Filter Change | 1.00 | $60.00 | $60.00 |

*Total service :* $60.00

**Service :** Replace Oil Pressure Switch (Service )

**Date :** 3/21/2022 **Technician responsible :** N/D **Cost :** $0.00

**Reference :** CHCS78253 **Vendor responsible :** Videon Dodge **Odometer :** 50,003

| Type | Description | Qty. | Unit cost | Total cost |
|---|---|---|---|---|
| Other | Replace Oil Pressure Switch | 1.00 | $0.00 | $0.00 |

*Total service :* $0.00

**Service :** Emission and State Insp., Replace Front Brakes and Rotors, Replace Cabin Filter and Wipers (Service )

**Date :** 3/28/2022 **Technician responsible :** N/D **Cost :** $604.00

**Reference :** 17857 **Vendor responsible :** Thorntons Gulf **Odometer :** 50,098

| Type | Description | Qty. | Unit cost | Total cost |
|---|---|---|---|---|
| Other | Emission and State Insp., Replace Front Brakes and Rotors, Replace Cabin Filter and Wipers | 1.00 | $604.00 | $604.00 |

*Total service :* $604.00

**Service :** Mount and Balance 1 tire (Service )

**Date :** 4/22/2022 **Technician responsible :** N/D **Cost :** $20.00

**Reference :** 18345 **Vendor responsible :** Thorntons Gulf **Odometer :** 51,480

| Type | Description | Qty. | Unit cost | Total cost |
|---|---|---|---|---|
| Other | Mount and Balance 1 tire | 1.00 | $20.00 | $20.00 |

*Total service :* $20.00

**Service :** Oil and Filter Change, Replace Wiper Blades (Service )

**Date :** 5/11/2022 **Technician responsible :** N/D **Cost :** $105.00

**Reference :** 18416 **Vendor responsible :** Thorntons Gulf **Odometer :** 52,100

| Type | Description | Qty. | Unit cost | Total cost |
|---|---|---|---|---|
| Other | Oil and Filter Change, Replace Wiper Blades | 1.00 | $105.00 | $105.00 |

*Total service :* $105.00

**Service :** Replace ESIM Assembly (Service )

**Date :** 6/7/2022 **Technician responsible :** N/D **Cost :** $312.85

**Reference :** CHCS81722 **Vendor responsible :** Videon Dodge **Odometer :** 53,815

| Type | Description | Qty. | Unit cost | Total cost |
|---|---|---|---|---|
| Other | Replace ESIM Assembly | 1.00 | $312.85 | $312.85 |
| | | | *Total service :* | $312.85 |

**Service :** Replace Driver seat outer shield, Recharge AC, Reattached Vaccume Hose (Service )

**Date :** 7/6/2022 **Technician responsible :** N/D **Cost :** $833.89

**Reference :** CHCS82994 **Vendor responsible :** Videon Dodge **Odometer :** 54,452

| Type | Description | Qty. | Unit cost | Total cost |
|---|---|---|---|---|
| Other | Replace Driver seat outer shield, Recharge AC, Reattached Vaccume Hose | 1.00 | $833.89 | $833.89 |
| | | | *Total service :* | $833.89 |

**Service :** Replace Oil Temp Sensor (Service )

**Date :** 8/4/2022 **Technician responsible :** N/D **Cost :** $138.55

**Reference :** CHCS84487 **Vendor responsible :** Videon Dodge **Odometer :** 55,934

| Type | Description | Qty. | Unit cost | Total cost |
|---|---|---|---|---|
| Other | Replace Oil Temp Sensor | 1.00 | $138.55 | $138.55 |
| | | | *Total service :* | $138.55 |

**Service :** Mount and Balance two Tires (Service )

**Date :** 8/4/2022 **Technician responsible :** N/D **Cost :** $60.00

**Reference :** 000409 **Vendor responsible :** Thorntons Gulf **Odometer :** 0

| Type | Description | Qty. | Unit cost | Total cost |
|---|---|---|---|---|
| Other | Mount and Balance two Tires | 1.00 | $60.00 | $60.00 |
| | | | *Total service :* | $60.00 |

**Service :** Oil and Filter Change (Service )

**Date :** 8/5/2022 **Technician responsible :** N/D **Cost :** $75.00

**Reference :** 000411 **Vendor responsible :** Thorntons Gulf **Odometer :** 55,938

| Type | Description | Qty. | Unit cost | Total cost |
|---|---|---|---|---|
| Other | Oil and Filter Change | 1.00 | $75.00 | $75.00 |

*Total service :* $75.00

**Service :** Replace both Front headlight Assemblys (Service )

**Date :** 8/26/2022 **Technician responsible :** N/D **Cost :** $920.00

**Reference :** 000517 **Vendor responsible :** Thorntons Gulf **Odometer :** 56,659

| Type | Description | Qty. | Unit cost | Total cost |
|---|---|---|---|---|
| Other | Replace both Front headlight Assemblys | 1.00 | $920.00 | $920.00 |

*Total service :* $920.00

**Service :** Oil and Filter Chnage, Replace Thermistate and Gaskets, Replace Radiator Clamp and coolant, Replace Windshield Wiper Blades. (Service )

**Date :** 10/24/2022 **Technician responsible :** N/D **Cost :** $223.00

**Reference :** **Vendor responsible :** Thorntons Gulf **Odometer :** 58,828

| Type | Description | Qty. | Unit cost | Total cost |
|---|---|---|---|---|
| Other | Oil and Filter Chnage, Replace Thermistate and Gaskets, Replace Radiator Clamp and coolant, Replace Windshield Wiper Blades. | 1.00 | $223.00 | $223.00 |

*Total service :* $223.00

**Service :** Replace AC Condenser and Recharge, Replace TIPM and Wire new connector, Replace Radiator (Service )

**Date :** 11/10/2022 **Technician responsible :** N/D **Cost :** $1,725.75

**Reference :** CHCS88794 **Vendor responsible :** Videon Dodge **Odometer :** 59,082

| Type | Description | Qty. | Unit cost | Total cost |
|---|---|---|---|---|
| Other | Replace AC Condenser and Recharge, Replace TIPM and Wire new connector, Replace Radiator | 1.00 | $1,725.75 | $1,725.75 |

| | |
|---|---|
| *Total service :* | $1,725.75 |

**Service :** Replace Water Pump, Refill with Antifreez, Radiator Hose, and O Ring (Service )

**Date :** 1/11/2023 **Technician responsible :** N/D **Cost :** $0.00
**Reference :** CHCS91596 **Vendor responsible :** Videon Dodge **Odometer :** 62,119

| Type | Description | Qty. | Unit cost | Total cost |
|---|---|---|---|---|
| Other | Replace Water Pump, Refill with Antifreez, Radiator Hose, and O Ring | 1.00 | $0.00 | $0.00 |
| | *Total service :* | | | $0.00 |

**Service :** Oil and Filter Change (Service )

**Date :** 1/18/2023 **Technician responsible :** N/D **Cost :** $75.00
**Reference :** **Vendor responsible :** Thorntons Gulf **Odometer :** 62,541

| Type | Description | Qty. | Unit cost | Total cost |
|---|---|---|---|---|
| Other | Oil and Filter Change | 1.00 | $75.00 | $75.00 |
| | *Total service :* | | | $75.00 |

**Service :** Replace Thrmostat and Seal along with Upper "O" ring (Service )

**Date :** 1/11/2023 **Technician responsible :** N/D **Cost :** $144.18
**Reference :** CHCS91744 **Vendor responsible :** Videon Dodge **Odometer :** 62,125

| Type | Description | Qty. | Unit cost | Total cost |
|---|---|---|---|---|
| Other | Replace Thrmostat and Seal along with Upper "O" ring | 1.00 | $144.18 | $144.18 |
| | *Total service :* | | | $144.18 |

**Service :** Replace Wiper Blades (Service )

**Date :** 1/20/2023 **Technician responsible :** N/D **Cost :** $36.00
**Reference :** **Vendor responsible :** Thorntons Gulf **Odometer :** 0

| Type | Description | Qty. | Unit cost | Total cost |
|---|---|---|---|---|
| Other | Replace Wiper Blades | 1.00 | $36.00 | $36.00 |

| | | | | | |
|---|---|---|---|---|---|
| | | | | *Total service :* | $36.00 |

**Service :** Emission and State Insp. Replace Rear Brakes (Service )

**Date :** 3/3/2023 **Technician responsible :** N/D **Cost :** $222.00

**Reference :** **Vendor responsible :** Thorntons Gulf **Odometer :** 63,454

| Type | Description | Qty. | Unit cost | Total cost |
|---|---|---|---|---|
| Other | Emission and State Insp. Replace Rear Brakes | 1.00 | $222.00 | $222.00 |
| | | | *Total service :* | $222.00 |

**Service :** Replace Left and Right Front Headlamps (Service )

**Date :** 3/15/2023 **Technician responsible :** N/D **Cost :** $1,216.00

**Reference :** CHCB94481 **Vendor responsible :** West Goshen Automotive **Odometer :** 63,782

| Type | Description | Qty. | Unit cost | Total cost |
|---|---|---|---|---|
| Other | Replace Left and Right Front Headlamps | 1.00 | $1,216.00 | $1,216.00 |
| | | | *Total service :* | $1,216.00 |

**Service :** Oil and Filter Change (Service )

**Date :** 3/16/2023 **Technician responsible :** N/D **Cost :** $75.00

**Reference :** **Vendor responsible :** Thorntons Gulf **Odometer :** 65,583

| Type | Description | Qty. | Unit cost | Total cost |
|---|---|---|---|---|
| Other | Oil and Filter Change | 1.00 | $75.00 | $75.00 |
| | | | *Total service :* | $75.00 |

**Service :** Oil and Filter Change (Service )

**Date :** 5/1/2023 **Technician responsible :** N/D **Cost :** $75.00

**Reference :** **Vendor responsible :** Thorntons Gulf **Odometer :** 66,311

| Type | Description | Qty. | Unit cost | Total cost |
|---|---|---|---|---|
| Other | Oil and Filter Change | 1.00 | $75.00 | $75.00 |

| | |
|---|---|
| *Total service :* | $75.00 |

**Service :** Oil and Filter Change (Service )

**Date :** 6/1/2023 **Technician responsible :** N/D **Cost :** $75.00

**Reference :** **Vendor responsible :** Thorntons Gulf **Odometer :** 69,447

| Type | Description | Qty. | Unit cost | Total cost |
|---|---|---|---|---|
| Other | Oil and Filter Change | 1.00 | $75.00 | $75.00 |
| | *Total service :* | | | $75.00 |

**Service :** Replace AC Driver Side Actuator door and gear (Service )

**Date :** 6/9/2023 **Technician responsible :** N/D **Cost :** $466.41

**Reference :** 100467 **Vendor responsible :** Videon Dodge **Odometer :** 70,127

| Type | Description | Qty. | Unit cost | Total cost |
|---|---|---|---|---|
| Other | Replace AC Driver Side Actuator door and gear | 1.00 | $466.41 | $466.41 |
| | *Total service :* | | | $466.41 |

**Service :** Oil and Filter Change (Service )

**Date :** 7/10/2023 **Technician responsible :** N/D **Cost :** $75.00

**Reference :** 18022 **Vendor responsible :** Thorntons Gulf **Odometer :** 72,636

| Type | Description | Qty. | Unit cost | Total cost |
|---|---|---|---|---|
| Other | Oil and Filter Change | 1.00 | $75.00 | $75.00 |
| | *Total service :* | | | $75.00 |

**Service :** Replace Front Brakes, Resurface front rotors, mount and balance 2 tires, alignment (Service )

**Date :** 9/21/2023 **Technician responsible :** N/D **Cost :** $424.00

**Reference :** **Vendor responsible :** Thorntons Gulf **Odometer :** 76,081

| Type | Description | Qty. | Unit cost | Total cost |
|---|---|---|---|---|
| Other | Replace Front Brakes, Resurface front rotors, mount and balance 2 tires, alignment | 1.00 | $424.00 | $424.00 |

alignment

| | |
|---|---|
| *Total service :* | $424.00 |

**Service :** Oil and Filter Change (Service )

**Date :** 9/19/2023 **Technician responsible :** N/D **Cost :** $75.00

**Reference :** **Vendor responsible :** Thorntons Gulf **Odometer :** 75,906

| Type | Description | Qty. | Unit cost | Total cost |
|---|---|---|---|---|
| Other | oil and filter change | 1.00 | $75.00 | $75.00 |
| | *Total service :* | | | $75.00 |

**Service :** Replace Heater Hoses Assembly, Refill Coolant (Service )

**Date :** 10/9/2023 **Technician responsible :** N/D **Cost :** $451.00

**Reference :** **Vendor responsible :** Thorntons Gulf **Odometer :** 76,706

| Type | Description | Qty. | Unit cost | Total cost |
|---|---|---|---|---|
| Other | Replace Heater Hoses Assembly, Refill Coolant | 1.00 | $451.00 | $451.00 |
| | *Total service :* | | | $451.00 |

**Service :** Replace Master Cylinder, Replace Power Booster (Service )

**Date :** 9/28/2023 **Technician responsible :** N/D **Cost :** $685.00

**Reference :** **Vendor responsible :** Thorntons Gulf **Odometer :** 76,251

| Type | Description | Qty. | Unit cost | Total cost |
|---|---|---|---|---|
| Other | Replace Master Cylinder, Replace Power Booster | 1.00 | $685.00 | $685.00 |
| | *Total service :* | | | $685.00 |

**Service :** Oil and Filter Change, Replace Windshield Wipers (Service )

**Date :** 12/15/2023 **Technician responsible :** N/D **Cost :** $111.00

**Reference :** **Vendor responsible :** Thorntons Gulf **Odometer :** 78,508

| Type | Description | Qty. | Unit cost | Total cost |
|---|---|---|---|---|

| | | | | |
|---|---|---|---|---|
| Other | Oil and Filter Change, Replace Windshield Wipers | 1.00 | $111.00 | $111.00 |
| | | | *Total service :* | $111.00 |

**Service :** Replace Alterrnator and replace serp belt, Replace rear driveshaft Assembly, Replace left motor mount (Service )

**Date :** 1/9/2024 **Technician responsible :** N/D **Cost :** $1,998.58
**Reference :** 109678 **Vendor responsible :** Videon Dodge **Odometer :** 79,529

| Type | Description | Qty. | Unit cost | Total cost |
|---|---|---|---|---|
| Other | Replace Alterrnator and replace serp belt, Replace rear driveshaft Assembly, Replace left motor mount | 1.00 | $1,998.58 | $1,998.58 |
| | | | *Total service :* | $1,998.58 |

**Service :** Oil and Filter Change (Service )

**Date :** 3/6/2024 **Technician responsible :** N/D **Cost :** $75.00
**Reference :** **Vendor responsible :** Thorntons Gulf **Odometer :** 82,102

| Type | Description | Qty. | Unit cost | Total cost |
|---|---|---|---|---|
| Other | Oil and Filter Change | 1.00 | $75.00 | $75.00 |
| | | | *Total service :* | $75.00 |

**Service :** Replace Refrigerant in Air Conditioner (Service )

**Date :** 3/12/2024 **Technician responsible :** N/D **Cost :** $509.40
**Reference :** 112582 **Vendor responsible :** Videon Dodge **Odometer :** 82,585

| Type | Description | Qty. | Unit cost | Total cost |
|---|---|---|---|---|
| Other | Replace Refrigerant in Air Conditioner | 1.00 | $509.40 | $509.40 |
| | | | *Total service :* | $509.40 |

**Service :** Replace Oil Cooler and Heat Hose,Replace 2 Upper Control Arms, Replace 2 Lower Ball Joints, Flush and Fill Coolant system, Emission and State Inspection, Front end allignment, Mount and Balance two tires. (Service )

**Date :** 3/29/2024 **Technician responsible :** N/D **Cost :** $1,713.00

**Reference :** **Vendor responsible :** Thorntons Gulf **Odometer :** 83,091

| Type | Description | Qty. | Unit cost | Total cost |
|---|---|---|---|---|
| Other | Replace Oil Cooler and Heat Hose,Replace 2 Upper Control Arms, Replace 2 Lower Ball Joints, Flush and Fill Coolant system, Emission and State Inspection, Front end allignment, Mount and Balance two tires. | 1.00 | $1,713.00 | $1,713.00 |
| | | | *Total service :* | $1,713.00 |

**Service :** Replace Driver Side Window switch (Service )

**Date :** 5/14/2024 **Technician responsible :** N/D **Cost :** $99.45

**Reference :** **Vendor responsible :** Videon Dodge **Odometer :** 0

| Type | Description | Qty. | Unit cost | Total cost |
|---|---|---|---|---|
| Other | Replace Driver Side Window switch | 1.00 | $99.45 | $99.45 |
| | | | *Total service :* | $99.45 |

**Service :** Oil and Filter Change, Mount and Balance 2 tires (Service )

**Date :** 5/23/2024 **Technician responsible :** N/D **Cost :** $105.00

**Reference :** **Vendor responsible :** Thorntons Gulf **Odometer :** 85,682

| Type | Description | Qty. | Unit cost | Total cost |
|---|---|---|---|---|
| Other | Oil and Filter Change, Mount and Balance 2 tires | 1.00 | $105.00 | $105.00 |
| | | | *Total service :* | $105.00 |

**Service :** Replace Lower Hose, Hood Strap and Coolant (Service )

**Date :** 6/20/2024 **Technician responsible :** N/D **Cost :** $320.00

**Reference :** **Vendor responsible :** Thorntons Gulf **Odometer :** 86,857

| Type | Description | Qty. | Unit cost | Total cost |
|---|---|---|---|---|
| Other | Replace Lower Hose, Hood Strap and Coolant | 1.00 | $320.00 | $320.00 |

| | |
|---|---|
| *Total service :* | $320.00 |

**Service :** Oil and Filter Change (Service )

**Date :** 7/29/2024 **Technician responsible :** N/D **Cost :** $75.00

**Reference :** **Vendor responsible :** Thorntons Gulf **Odometer :** 88,246

| Type | Description | Qty. | Unit cost | Total cost |
|---|---|---|---|---|
| Other | Oil and Filter Change | 1.00 | $75.00 | $75.00 |
| | *Total service :* | | | $75.00 |

**Service :** Replace Battery (Service )

**Date :** 9/9/2024 **Technician responsible :** N/D **Cost :** $500.00

**Reference :** **Vendor responsible :** Thorntons Gulf **Odometer :** 90,278

| Type | Description | Qty. | Unit cost | Total cost |
|---|---|---|---|---|
| Other | Replace Battery | 1.00 | $500.00 | $500.00 |
| | *Total service :* | | | $500.00 |

**Service :** Oil and Filter Change, Fill Coolant (Service )

**Date :** 9/20/2024 **Technician responsible :** N/D **Cost :** $100.00

**Reference :** **Vendor responsible :** Thorntons Gulf **Odometer :** 91,404

| Type | Description | Qty. | Unit cost | Total cost |
|---|---|---|---|---|
| Other | Oil and Filter Change, Fill Coolant | 1.00 | $100.00 | $100.00 |
| | *Total service :* | | | $100.00 |

*Total of the vehicle :* *$39,104.27*