Work History Report

Date Produced: 10/12/2026
Account: 18 Prison
Reg: 52457-MG PA
Vehicle Details CHEVROLET TAHOE 5.3 2002

Cumberland County Courthouse
310 Allen Road
Suite 501
Carlisle
PA
17013-3323

Eng Code / Num V8 5.3L 323CID FI FLEX N Z / **Vin** 1GNEK13Z72J290757 **Mileage** 106817

Invoice Number I004361 **Date** 4/7/2026 **Mileage** 106817 **Job Value** 65.55
Vehicle Details 52457-MG PA CHEVROLET TAHOE 2002

Labor	Value
State Inspection	33.68
State Emission Inspection	28.07

Parts		Qty	Value
CNVEMI	Emissions, Phone Transaction Fee	1.00	1.80

Invoice Number I003699 **Date** 3/6/2025 **Mileage** 105245 **Job Value** 562.04
Vehicle Details 52457-MG PA CHEVROLET TAHOE 2002

Labor	Value
PM Service check lights,brake and overall safety of vehicle	33.35
State Emission Inspection	27.79
State Inspection	33.35
Rotate Tires	11.12
Shop Labor- Cumberland County. Ball joint is loose. Replaced left front upper control arm.	83.37
Shop Labor- Cumberland County. Rear caliper pins rusted tight. Replaced both rear calipers, rear brakes and bled.	111.16

Parts		Qty	Value
CNVWWFliud Clearv	Windshield Washer Fluid	1.00	1.35
CNV75-053	5W30 Oil syn blend	6.00	10.38
CNVEMI	Emissions, Phone Transaction Fee	1.00	1.57
CNV85042	Oil Filter	1.00	2.65
CNVGCA10273	Upper Control Arm + Ball Joint	1.00	85.99
CNV18-B4765	Brake Caliper	1.00	55.99
CNV18-B4764	Brake Caliper	1.00	55.99
CNVDG834	Rear Brake Pads	1.00	38.99
CNVAB32AZ	Brake Fluid	1.00	4.99

Invoice Number I002962 **Date** 1/10/2024 **Mileage** 101095 **Job Value** 152.71
Vehicle Details 52457-MG PA CHEVROLET TAHOE 2002

Labor	Value
PM Service check lights,brake and overall safety of vehicle. Gas Cap missing installed new tethered cap. Heater not working, found plug unhooked, resecured connectors and checked blower. Working at this time.	55.15
State Inspection	33.09
State Emission Inspection	27.58

Parts		Qty	Value
CNVWWFliud Clearv	Windshield Washer Fluid	1.00	1.32
CNV75-053	5W30 Oil syn blend	6.00	15.30
CNVEMI	Emissions, Phone Transaction Fee	1.00	1.57
CNV85042	Oil Filter	1.00	2.62
CNVMGC817T	Gas Cap	1.00	14.08

Invoice Number I002371 **Date** 3/7/2023 **Mileage** 99338 **Job Value** 540.98
Vehicle Details 52457-MG PA CHEVROLET TAHOE 2002

Labor	Value
Service Call to prison, Tahoe shut off. Found vehicle to have no fuel pressure, vehicle was towed to 1601	51.75
Drained fuel tank, removed fuel tank and cleaned around fuel pump, installed new fuel and refilled	155.25

Parts		Qty	Value
CNVTR19	Fuel Tank Lock Ring	1.00	15.99
CNVDFG0810	Delphi Fuel Pump	1.00	240.99
CNVTOWING	JERRY TOWING INVOICE #168520	1.00	75.00

Invoice Number I002358 **Date** 3/1/2023 **Mileage** 99205 **Job Value** 58.50

Vehicle Details 52457-MG PA CHEVROLET TAHOE 2002

Labor	Value
State Emission Inspection	25.88
State Inspection	31.05

Parts		Qty	Value
CNVEMI	Emissions, Phone Transaction Fee	1.00	1.57

Invoice Number I002354 **Date** 2/28/2023 **Mileage** 99199 **Job Value** 709.84

Vehicle Details 52457-MG PA CHEVROLET TAHOE 2002

Labor	Value
PM Service check lights,brake and overall safety of vehicle	31.05
Rotate Tires	15.53
Replaced wiper blades.	10.35
Shop Labor- Cumberland County. Blower motOr bearing is noisy. Replaced blower motor and cabin air filter.	51.75
Shop Labor- Cumberland County. Replaced main drive belt, tensioner and idler pulley from kit. Replaced a/c belt and tensioner with kit.	77.63
Shop Labor- Cumberland County. Both front lamps full of water, bulbs burnt out. Replaced right and left front turn signal lamps. Replaced all bulbs.	41.40
Shop Labor- Cumberland County. SES light on. Checked codes, has code P0171 + P0174. Checked for vacuum leaks and found intake is leaking vacuum. Replaced intake and throttle body gaskets. Cleaned throttle bore and cleared codes.	181.13

Parts		Qty	Value
CNVWWFliud Clearv	Windshield Washer Fluid	1.00	1.20
CNV75-053	5W30 Oil syn blend	6.50	20.67
CNV85042	Oil Filter	1.00	2.62
CNVDL22 / az	Wiper Blade	2.00	6.00
CNVPM2728	Blower Motor	1.00	47.99
CNV90006PT	Cabin Air Filter	1.00	10.14
CNVD60930K1	Drive Belt Kit	1.00	66.98
CNV5040378K1	A/C Belt Kit	1.00	33.10
CNV12-5100-01	Lamp Assembly left	1.00	19.99
CNV12-5099-01	Lamp Assembly right	1.00	24.99
CNV194	Light Bulb	2.00	1.34
CNV3157NA	Light bulbamber	2.00	3.70
CNV4157	Light Bulb /driving light	2.00	3.90
CNVMS16340	Intake Gaskets	1.00	46.79
CNV61070	Throttle Body Gasket	1.00	5.59

Invoice Number I001794 **Date** 4/22/2022 **Mileage** 95740 **Job Value** 192.07

Vehicle Details 52457-MG PA CHEVROLET TAHOE 2002

Labor	Value
Power steering fluid leaking, found steering cooler rusted apart. Removed cooler and lines, installed new cooler and lines. Cleaned fluid off as best as possible.	100.50

Parts		Qty	Value
CNV918-301	Oil Cooler Assembly	1.00	83.79
CNVAZPSF32AZ	Power Steering Fluid	1.00	2.78

Invoice Number I001661 **Date** 2/8/2022 **Mileage** 94821 **Job Value** 115.44

Vehicle Details 52457-MG PA CHEVROLET TAHOE 2002

Labor	Value
State Inspection	30.15
State Emission Inspection	25.13
Wiper washer pump inoperative, power and ground at pump connector. Faulty washer Pump R&R washer pump.	40.20

Parts		Qty	Value
CNVEMI	Emissions, Phone Transaction Fee	1.00	1.57
CNV6-700	Washer Pump	1.00	16.39

Invoice Number I001235 **Date** 6/15/2021 **Mileage** 93768 **Job Value** 29.61

Vehicle Details 52457-MG PA CHEVROLET TAHOE 2002

Labor	Value
Replace battery under warranty, checked charging system for draw. Found battery was faulty	27.61

Parts		Qty	Value
CNVUL78	Battery *UNDER WARRANTY*	1.00	0.00

Invoice Number I001218 **Date** 6/3/2021 **Mileage** 93760 **Job Value** 62.85

Vehicle Details 52457-MG PA CHEVROLET TAHOE 2002

Labor	Value
PM Service check lights,brake and overall safety of vehicle	27.61

Replaced wiper blades.	9.20	d Clearv	Windshield Washer Fluid	1.00	1.15
		CNVDL22 / az	Wiper Blade	2.00	6.00
		CNVPH3675	Oil Filter	1.00	3.99

Invoice Number I001206 **Date** 5/27/2021 **Mileage** 93713 **Job Value** 137.30

Vehicle Details 52457-MG PA CHEVROLET TAHOE 2002

Labor	Value	Parts		Qty	Value
Battery testing weak, cleaned terminals and replaced battery	23.01	CNVUL78	East Penn Battery 36 Month Warranty	1.00	112.29

Advisory Original License Plate CNV002D PA changed on 06/03/2021

Invoice Number K11112 **Date** 1/7/2021 **Mileage** 87064 **Job Value** 617.54

Vehicle Details 52457-MG PA CHEVROLET TAHOE 2002

Work Description NULL
NULL
State Inspection
Found blower motor resistor plug melted replaced blower motor resistor. Replaced air and cabin filter while apart.
Replaced Front Brake and rotors cleaned and lubed caliper pins
Replaced rear brake pads and rotors cleaned and lubed caliper pins
Replaced wiper blades
Mounted and balanced tires with 4 good used tires.
NULL

Labor	Value	Parts		Qty	Value
State Emissions Inspection	23.01	CNVCAF1707AZ	Cabin Air Filter	1.00	10.99
Emissions Phone Transaction Fee	1.57	CNVSA8755AZ	Air Filter	1.00	7.99
State inspection	27.61	CNVDR775AZ	Blower Motor Resistor	1.00	28.29
Blower Motor not working	46.02	CNVQX785 Fisher	Silent Stop Front Brake Pads	1.00	33.66
Front Brakes Rotors	69.03	CNVSB56825Fisher	Front Brake Rotor	2.00	63.06
Rear BrakesRotors	69.03	CNVDG834AZ	Duralast Gold Rear Brake Pads	1.00	27.92
replace wiper blades	9.20	CNV55067DGAZ	Duralast Gold Front Brake Rotor	2.00	102.08
Change Tires	69.03	CNVDL22 az	Wiper Blade	2.00	6.00
Tire Disposal Fee 4 tires Highlands	8.00	CNV24120 Myers	Valve Stem 1.25 Metal Pull through	4.00	5.04
		CNV333333	Wheel Weights	8.00	4.00

Advisory Original License Plate CNV002D PA changed on 06/03/2021

Invoice Number K10431 **Date** 1/15/2020 **Mileage** 85406 **Job Value** 101.19

Vehicle Details 52457-MG PA CHEVROLET TAHOE 2002

Work Description Lube Oil Filter Changed checked Brakes Lights wipers and over all safety.
NULL
NULL
State Inspection

Labor	Value	Parts		Qty	Value
Service	26.53	CNVWWFliud	Windshield Washer Fluid	1.00	1.15
State Emissions Inspection	21.22	CNV5w-30 Petro	Oil	6.00	12.90
Emissions Phone Transaction Fee	1.57	CNVPH3675AZ	Oil Filter	1.00	3.99
State inspection	31.83				

Advisory Original License Plate CNV002D PA changed on 06/03/2021

Invoice Number K9476 **Date** 11/16/2018 **Mileage** 81768 **Job Value** 103.24

Vehicle Details 52457-MG PA CHEVROLET TAHOE 2002

Work Description Lube Oil Filter Changed checked Brakes Lights wipers and over all safety.
NULL
NULL
State Inspection

Labor	Value
Service	28.10
State Emissions Inspection	22.48
Emissions Phone Transaction Fee	1.65
State inspection	33.72

Parts		Qty	Value
CNVWWFliud	Windshield Washer Fluid	1.00	1.15
CNV5w-30 Petro	Oil	6.00	11.10
CNVPH3675BC	Oil Filter	1.00	3.04

Advisory Original License Plate CNV002D PA changed on 06/03/2021

Invoice Number K8955 **Date** 3/23/2018 **Mileage** 79579 **Job Value** 575.33

Vehicle Details 52457-MG PA CHEVROLET TAHOE 2002

Work Description Had Jerrys Towing tow back to garage from prison due to Brake line being broken.
Found leaking brake line. Removed all brake lines and replaced due to them all showing signs of age and rusting.
NULL

Labor	Value
Towed to Garage from Prison	65.00
Check brake fluid leak.	393.40
Rotate Tires	16.86

Parts		Qty	Value
CNV229332 17 Graham	Brake Line Kit	1.00	79.57
CNVCNC-4 25 az	Brake Line 14 inch nicklecopper per foot	6.00	10.44
CNVAS401yaz	Brake Fluid	1.00	4.17
CNV13908	Brake Bleeders Front	1.00	3.89

Advisory Original License Plate CNV002D PA changed on 06/03/2021

Invoice Number K8693 **Date** 12/7/2017 **Mileage** 78630 **Job Value** 59.37

Vehicle Details 52457-MG PA CHEVROLET TAHOE 2002

Work Description NULL
NULL
State Inspection

Labor	Value
State Emissions Inspection	23.09
Emissions Phone Transaction Fee	1.65
State inspection	34.63

Parts	Qty	Value

Advisory Original License Plate CNV002D PA changed on 06/03/2021

Invoice Number K8061 **Date** 3/3/2017 **Mileage** 75900 **Job Value** 75.85

Vehicle Details 52457-MG PA CHEVROLET TAHOE 2002

Work Description Lube Oil Filter Changed checked Brakes Lights wipers and over all safety.
Checked tire for leaks. Found bead leaking. removed tire and cleaned rim. Remounted and balanced tire.

Labor	Value
Service	28.86
Check mLow Tire	28.86

Parts		Qty	Value
CNVWWFliud	Windshield Washer Fluid	1.00	1.15
CNV5w-30 Petro	Oil	6.00	8.94
CNVPH3675BC	Oil Filter	1.00	3.04
CNV333333	Wheel Weights	2.00	1.00

Advisory Original License Plate CNV002D PA changed on 06/03/2021

Invoice Number K7889 **Date** 12/9/2016 **Mileage** 75286 **Job Value** 128.99

Vehicle Details 52457-MG PA CHEVROLET TAHOE 2002

Work Description Checked front suspension and ball joints. o.k. Checked steering and found steering shaft making clunking noise. Replaced intermediate steering shaft.

Labor	Value	Parts		Qty	Value
Steering makes a knocking noise when turning wheel	58.24	CNV425-17 6 az	Steering Shaft	1.00	68.75

Advisory Original License Plate CNV002D PA changed on 06/03/2021

Invoice Number K7759 **Date** 10/7/2016 **Mileage** 72570 **Job Value** 344.48

Vehicle Details 52457-MG PA CHEVROLET TAHOE 2002

Work Description Lube Oil Filter Changed checked Brakes Lights wipers and over all safety.
NULL
NULL
State Inspection
plugged hole in tire
NULL
NULL
NULL
Changed rear end oil
Replaced right driving light bulb and both front side marker bulbs.

Labor	Value	Parts		Qty	Value
Service	29.12	CNVWWFliud	Windshield Washer Fluid	1.00	1.15
State Emissions Inspection	23.30	CNV5w-30 Petro	Oil	6.00	8.94
Emissions Phone Transaction Fee	1.65	CNVPH3675 BC	Oil Filter	1.00	3.19
State inspection	34.94	CNV710-10 36 .Napa	tire plug	1.00	1.00
plug tire	14.56	CNV890010 16 Graham	Wiper Blade 22 inch	2.00	15.90
Rotate Tires	11.65	CNVMT-78 INT	Interstate Battery	1.00	91.95
Replace blades	11.65	CNV104361 AZ	Mobil 1 Synthetic 75w-90	2.00	21.00
Change Battery	29.12	CNVLT4157 LLBX AZ	Light Bulb	1.00	2.00
Change rear end oil	17.47	CNVLT194B X AZ	Light Bulb 194	2.00	0.60
Right driving light and both front side bulbs are out	23.30				

Advisory Original License Plate CNV002D PA changed on 06/03/2021

Invoice Number K6985 **Date** 10/30/2015 **Mileage** 61673 **Job Value** 95.55

Vehicle Details 52457-MG PA CHEVROLET TAHOE 2002

Work Description Lube Oil Filter Changed
NULL
NULL
NULL

Labor	Value	Parts		Qty	Value
Service	26.35	CNVWWFliud	Windshield Washer Fluid	1.00	1.15
State Emissions Inspection	21.08	CNV5w-30 Petro	Oil	6.00	8.94
Emissions Phone Transaction Fee	1.47	CNVPH3675 BC	Oil Filter	1.00	2.94
State Inspection	31.62				

Advisory Original License Plate CNV002D PA changed on 06/03/2021

Invoice Number K6497 **Date** 4/13/2015 **Mileage** 54924 **Job Value** 97.34

Vehicle Details 52457-MG PA CHEVROLET TAHOE 2002

Work Description Lube Oil Filter Changed
Removed spare tire from rim and mounted and balanced tire on left front rim. Mounted a good used tire on the spare tire rim and put spare tire back.

Labor	Value
Service	26.35

left front tire went flat spare was put on	52.70	CNVPH3675 BC	Oil Filter	1.00	2.94
		CNV24120 Myers	Valve Stem 1.25 Metal Pull through	1.00	1.26

Advisory Original License Plate CNV002D PA changed on 06/03/2021

Invoice Number K6391 **Date** 3/4/2015 **Mileage** 53287 **Job Value** 398.27

Vehicle Details 52457-MG PA CHEVROLET TAHOE 2002

Work Description Checked for noise found rear parking brake shoe lining came off. Metal shoe wore in rotor. Replaced both rear parking brake shoes and rebuilt right parking brake actuator.
Replaced rear brakes and rotors

Labor	Value
noise in rear backing up	144.93
replace rear brakes and rotors	79.05

Parts		Qty	Value
CNVH7927 az	brake rebuild kit	1.00	15.19
CNV781 az	parking brake shoes	1.00	52.07
CNVDGC83 4 az	rear brakes	1.00	44.99
CNV55067 az	Brake RotorDisc	2.00	58.04

Advisory Original License Plate CNV002D PA changed on 06/03/2021

Invoice Number K6089 **Date** 10/10/2014 **Mileage** 50417 **Job Value** 115.04

Vehicle Details 52457-MG PA CHEVROLET TAHOE 2002

Work Description Lube Oil Filter Changed
NULL
NULL
NULL
NULL
Replaced left rear tire valve stem

Labor	Value
Service	25.31
Rotate Tires	16.88
State Emissions Inspection	16.88
Emissions Phone Transaction Fee	1.47
State Inspection	25.31
left rear tire has a slow leak	12.66

Parts		Qty	Value
CNVWWFliu d	Windshield Washer Fluid	1.00	1.15
CNV5w-30 Petro	Oil	6.00	8.94
CNVPH3675 BC	Oil Filter	1.00	2.94
CNV22222	Valve Stem 1.5 Rubber	1.00	1.50

Advisory Original License Plate CNV002D PA changed on 06/03/2021

Invoice Number K5343 **Date** 10/8/2013 **Mileage** 41279 **Job Value** 133.07

Vehicle Details 52457-MG PA CHEVROLET TAHOE 2002

Work Description Lube Oil Filter Changed
NULL
NULL
NULL
NULL
NULL

Labor	Value
Service	27.05
Rotate Tires	18.03
State Emissions Inspection	18.03
Emissions Phone Transaction Fee	1.47
State Inspection	27.05
Replace blades	11.27

Parts		Qty	Value
CNVWWFliu d	Windshield Washer Fluid	1.00	0.99
CNV5w-30 Petro	Oil	6.00	10.74
CNVPH3675 BC	Oil Filter	1.00	2.94
CNVCWP22 -51-CQ	Windshield Wiper Blade	2.00	13.50

Advisory Original License Plate CNV002D PA changed on 06/03/2021

Invoice Number K5161 **Date** 7/9/2013 **Mileage** 39297 **Job Value** 67.62

Vehicle Details 52457-MG PA CHEVROLET TAHOE 2002

Work Description Diagnose engine codes. P0440 Check for evap leak. Checked vents on top of fuel tank. Checked tank pressure sensor. All checked good. Found Fuel cap tether stuck under fuel cap. Removed tether to avoid future problem. Tested system. no codes found.

Labor	Value	Parts		Qty	Value
Check Engine light on	67.62				

Advisory Original License Plate CNV002D PA changed on 06/03/2021

Invoice Number K5123 **Date** 6/20/2013 **Mileage** 38901 **Job Value** 12.25

Vehicle Details 52457-MG PA CHEVROLET TAHOE 2002

Work Description Replaced right brake light bulb

Labor	Value	Parts		Qty	Value
right brake light out	11.27	CNV3057	Light Bulb	1.00	0.98

Advisory Original License Plate CNV002D PA changed on 06/03/2021

Invoice Number K4806 **Date** 1/17/2013 **Mileage** 36697 **Job Value** 594.91

Vehicle Details 52457-MG PA CHEVROLET TAHOE 2002

Work Description Checked cold air issue. found vent cover for cabin air filter missing. Removed wrong cabin air filters and replaced missing cover.
Installed Step Bars

Labor	Value	Parts		Qty	Value
Check cold air coming from vents.	22.54	CNVCAF1707 AZ	Cabin Air Filters	1.00	12.59
Install Step Bars	90.16	CNV52494070 Graham	Filter Cover	1.00	5.67
		CNV22-5020 AZ	Step Bars	1.00	349.95
		CNV22-1135 AZ	Mounting Kit	1.00	110.00

Advisory Original License Plate CNV002D PA changed on 06/03/2021

Invoice Number K4703 **Date** 11/16/2012 **Mileage** 35996 **Job Value** 182.70

Vehicle Details 52457-MG PA CHEVROLET TAHOE 2002

Work Description Installed front and rear security cages in vehicle.

Labor	Value	Parts		Qty	Value
Install Security Cage in vehicle	182.70				

Advisory Original License Plate CNV002D PA changed on 06/03/2021

Invoice Number K4550 **Date** 9/12/2012 **Mileage** 35996 **Job Value** 116.85

Vehicle Details 52457-MG PA CHEVROLET TAHOE 2002

Work Description NULL
Emissions Inspection
NULL
Lube Oil Filter Changed
replaced left driving light bulb
installed mobile radio charger

Labor	Value	Parts		Qty	Value
State Inspection	24.36	CNVph3675	Oil Filter	1.00	3.59
Emissions Inspection	16.24	CNVWWFluid	Windshield Washer Fluid	1.00	0.99
Emissions Phone Transaction Fee	2.40	CNV5w-30 Petro	Oil	6.00	10.74
Service	24.36	CNV4157	Light Bulb	1.00	1.75
bulb	12.18				
radio charger	16.24				

Advisory Original License Plate CNV002D PA changed on 06/03/2021