**Rohrer's Service Center**
16 Lititz Road - PO Box 365
Lititz, PA. 17543
Phone: (717)-626-9756 | Fax: (717)-626-9424

Estimate # 210686

# Estimate

**Estimate Due: $4,524.66**

| | | | |
|---|---|---|---|
| **02929 Penn Twp Municipality -** | **2010 Ford - Pickup - F250 Super Duty** | Estimate Date: | 02/03/2026 |
| 97 N Penryn Rd | 5.4L, V8 (330CI) VIN(5) | Service Advisor: | |
| Manheim, PA 17545 | VIN: 1FTSX2B58 **AEB38608** License Plate: MG8428E PA | Customer ID: | 1794 |
| Home: 717-278-4698 | Odometer: In 0 | | |
| Cellular: 717-808-5045 | Unit: acc# 2929 | | |

| Type | Description | Part # | Qty/Hr | Sale | Total |
|---|---|---|---|---|---|
| **Check engine light on** | | | | Initials: | **$2,900.48** |
| Labor | Check engine light on<br>Found code for P0430 bank 2 catalyst. Catalytic converter is sold as a y-pipe assembly. Y-pipe attaches to the exhaust manifolds, which are in poor condition. Passenger side exhaust manifold is rusty and leaking. Driver's side exhaust manifold is not leaking, but all of the bolt heads are rusted off. May require quite a bit of time to remove manifolds and extract bolts. Quote is approximate time, may take less or more time. | | 10.00 hr | | $1,050.00 |
| Part | Catalytic converter y-pipe assembly | | 1.00 | $1,079.64 | $1,079.64 |
| Part | Manifold | | 1.00 | $325.50 | $325.50 |
| Part | Manifold | | 1.00 | $255.50 | $255.50 |
| Part | Manifold gaskets | | 4.00 | $33.46 | $133.84 |
| Part | Manifold hardware | | 2.00 | $28.00 | $56.00 |

Parts: $1,850.48 Labor: $1,050.00 Tax: $0.00 Total: $2,900.48

| | | | | | |
|---|---|---|---|---|---|
| **Check noise over bumps** | | | | Initials: | **$605.86** |
| Labor | Check noise over bumps<br>Found 4 of the cab mounts are bad. Quote is approximate time, have had issues in the past removing rusty cab mount bolts. May take less or more time. May require more parts if we need hardware to reinstall if bolts break. | | 4.00 hr | | $420.00 |
| Part | Cab mount | | 2.00 | $57.68 | $115.36 |
| Part | Cab mount | | 2.00 | $35.25 | $70.50 |

Parts: $185.86 Labor: $420.00 Tax: $0.00 Total: $605.86

| | | | | | |
|---|---|---|---|---|---|
| **Check bearing noise** | | | | Initials: | **$843.32** |
| Part | Wheel bearing assembly | | 1.00 | $633.32 | $633.32 |
| Labor | Check bearing noise<br>Bearing noise is coming from R/F wheel bearing assembly. Recommend replacing R/F wheel bearing assembly. | | 2.00 hr | | $210.00 |

Parts: $633.32 Labor: $210.00 Tax: $0.00 Total: $843.32

| | | | | | |
|---|---|---|---|---|---|
| **Check blower motor only works on "max"** | | | | Initials: | **$140.00** |
| Labor | Check blower motor only works on "max"<br>Needs blower motor resistor for blower to operate properly. | | 0.50 hr | | $52.50 |
| Part | Blower motor resistor | | 1.00 | $87.50 | $87.50 |

Parts: $87.50 Labor: $52.50 Tax: $0.00 Total: $140.00

Copyright © Mitchell Repair Information Company LB1124E

| Type | Description | Part # | Qty/Hr | Sale | Total |
|---|---|---|---|---|---|
| **Notes** | | | | Initials: | **$0.00** |
| Note | Found hole in bed at R/R floor, would need to be addressed for inspection. Also, noticed bed rails are starting to rot (bed would need to be removed to have bed rails done) , may need addressed in the future for inspection if they get worse. Recommend body shop for those repairs. Overall, unit is starting to get very rusty. | | | | |

Parts: $0.00 Labor: $0.00 Tax: $0.00 Total: $0.00

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the vehicle described for testing and/or inspection. Express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto. SMOG: I understand that I can have emission service and/or adjustments done elsewhere. I hereby waive this right. TEARDOWN ESTIMATE: I understand that my vehicle will be reassembled within____days of the date shown above if I choose not to authorize the service recommended. All Parts removed will be discarded unless instructed otherwise: Save all Parts____. NOT RESPONSIBLE FOR LOSS OR DAMAGE TO CARS OR ARTICLES LEFT IN CARS IN CASE OF FIRE, THEFT OR ANY OTHER CAUSE.

| | |
|---|---|
| Labor | $1,732.50 |
| Parts | $2,757.16 |
| Shop Supplies | $35.00 |
| **Subtotal** | **$4,524.66** |
| Taxes | $0.00 |
| **Estimate Total:** | **$4,524.66** |

Signature _____ Date _____ Time _____

Copyright © Mitchell Repair Information Company LB1124E