FixFinder©

2011 GMC Canyon WT
4 Cylinders 2.9L

VIN: 1GTJ6LF92B8******
Odometer: 158,000 MI

Scanned on
Thursday, Oct 29, 2026, 9:36 AM
Report #
dd1f3J
Store #
06095

TEST RESULTS SUMMARY

Check Engine	ABS	Emission Ready	Service Interval	TPMS
FAIL	PASS	NO	PASS	FAIL

Emission Ready = NO: This vehicle is not **ready** for emission testing. Reference the **Recommended Solutions and Diagnostic Trouble Codes** section below to determine what is needed to make your vehicle ready for emission testing. If trouble codes were recently cleared - vehicle must be driven a minimum of 50 miles to accurately determine Emission Readiness

MOST LIKELY SOLUTION

Replace Engine Variable Valve Timing (VVT) Solenoid

Suggested Parts: 1

PHOTO COMING SOON

Additional Part Required

Diagnostics was unable to find the part listed in the catalog, please use Z-net to search for the part listed under the Most Likely Solution

TEST RESULTS

Power Train System

P0017

Confirmed
Crankshaft Position - Exhaust Camshaft Position Not Plausible

Code P0017 indicates that the crankshaft and camshaft Bank 1 Sensor 'B' position signals did not correspond with each other with other for a predetermined period of time.

Secondary DTCs

P0017	Crankshaft Position - Exhaust Camshaft Position Not Plausible
P0014	Exhaust Camshaft Position System Performance

P0442	Evaporative Emission (EVAP) System Small Leak Detected
P0496	Evaporative Emission (EVAP) System Flow During Non-Purge
P0017	Crankshaft Position - Exhaust Camshaft Position Not Plausible
P0442	Evaporative Emission (EVAP) System Small Leak Detected
P0496	Evaporative Emission (EVAP) System Flow During Non-Purge
P0017	Crankshaft Position - Exhaust Camshaft Position Not Plausible
P0442	Evaporative Emission (EVAP) System Small Leak Detected
P0496	Evaporative Emission (EVAP) System Flow During Non-Purge

TPMS

Secondary DTCs

C0750	Left Front Low Tire Pressure Sensor Malfunction
C0755	Right Front Low Tire Pressure Sensor Malfunction
C0760	Left Rear Low Tire Pressure Sensor Malfunction
C0765	Right Rear Low Tire Pressure Sensor Malfunction
C0750	Left Front Low Tire Pressure Sensor Malfunction
C0755	Right Front Low Tire Pressure Sensor Malfunction
C0760	Left Rear Low Tire Pressure Sensor Malfunction
C0765	Right Rear Low Tire Pressure Sensor Malfunction

ADDITIONAL SYSTEM STATUS



Battery Voltage 12.30 V

Expected voltage between 11.2V and 13.0V - If over 13.0V Ensure vehicle is not running, but vehicle is in 'Run' mode and gauges are active.

What to check

Inspect the battery terminals to see if they are clean and tight - including between the terminal and the battery post